M.I.C.M. - C.N.I.A.R.
INTREPRINDEREA DE CONSTRUCTII AERONAUTICE
2200 B R A S O V

MANDATORY SERVICE BULLETIN

IS-28B2/EO-6

Approved by	:	Department of Civil Aviation with no. 345 / 8.01.1979
Product	:	IS-28B2 glider.
Object	:	Fixing the front seat back rod.
Compliance	:	Revision Record Card no.540, 662.

DATE: 04.01.1979

1. PLANNING INFORMATION

A. Applicability

This bulletin is applied by the user to gliders serial no. up to 130 inclusive. To gliders beginning with serial no. 131 the modification is applied by the manufacturing plant. It is applied until the 1st of March 1979, not later.

B. Reason

Impeding the lateral movement of the front seat.

C. Description

1. Fixing the front seat back with rivet
2. Checking and adjusting the front seat back rod clearance according to Appendix I.

D. Compliance

Revision Record Card: 540, 662.

E. Accomplishment

To gliders under manufacturing this bulletin is applied as current modification.

To gliders under servicing it is applied by the user not later than the 1st of March 1979.

F. Material-Cost and Availability

Materials necessary to apply this bulletin are specified in chapter 3.
Application belongs to the user.

G. Tooling

None.

I. References

See Appendix I.

J. Affected Documents

None.

2. ACCOMPLISHMENT INSTRUCTIONS

A. Preparation

Use the tool kit.

B. Application

1. Fixing the front seat back with rivet according to Appendix I.
2. Checking and adjusting the front seat back rod clearance according to the indications in Appendix I.

C. Using instructions

None.

3. MATERIAL INFORMATION

A. Material list

POP TLP/K/424/BS is recommended 1 pcs.

B. Tooling list


None.

4. IDENTIFICATION

The modifications application is mentioned in the glider logbook.

5. APPENDICES

None.


INFORMATIVELY
RIVET
VIEW ON ARROW „V"
ADJUSTING AND FIXING SCREWS
FOR SIZES A-B AND CLEARANCE 0,5
V
95
A
B
D.Z.
GLIDER AXLE
A - B
REAR SEAT BACK ROD
INFORMATIVELY